

REPAIR OF LONGITUDINAL DAMAGE IN TEXTILE BELT.

PROBLEM

20 m (65 ft) of longitudinal damage on the cover of a textile conveyor belt transporting lump iron ore.



PRODUCT APPLIED FLEXSOL BF-01


Coverage: 20 m.

Total material applied: 10 kits @ 110.23 lbs. / 50 kg.

Curing time 1 hr.

SOLUTION

Repair was done in less than 1 hour. FLEXSOL BF-01 was applied by 2 field technicians on site.



APPLICATION CONDITIONS Timetable




Start
15:00 (07-03-2024)



End
16:00 (07-03-2024)




BEFORE



PREPARATION: 30 min.



APPLICATION: 30 min.



AFTER

RESULTS

The belt was swiftly restored to full operation with minimal downtime and only two personnel required for the task, ensuring maximum efficiency in equipment performance.

